

TEMPERATURE CONVERSIONS

Conversion Formula :	
°C X 1.8 plus 32 equals	°F
°F - 32 ÷ 1.8 equals	°C

Celsius	Fahrenheit
-50	-58.0
-40	-40.0
-30	-22.0
-24	-13.0
-20	-4.0
-15	-5.0
-10	14.0
-5	23.0
0	32.0
5	41.0
10	50.0
15	59.0
20	68.0
25	77.0
30	86.0
35	95.0
40	104.0
45	113.0
50	122.0
60	140.0

Celsius	Fahrenheit
70	158.0
80	176.0
90	194.0
100	212.0
110	230.0
120	248.0
130	266.0
140	284.0
150	302.0
160	320.0
170	338.0
180	356.0
190	374.0
200	392.0
210	410.0
220	428.0
230	446.0
240	464.0
250	482.0
537.7	1,000.0